

PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Patent No.: 7,346,711 B1 Docket: 60046.0062US01  
Issue Date: March 18, 2008 Patentee: Datta Roy et al.  
Title: Methods, Systems, and Computer Program Products for Detecting IDE  
Device Connections

---

REQUEST FOR CERTIFICATE OF CORRECTION

Certificate of Correction Branch  
Commissioner for Patents  
P.O. Box 1450  
Alexandria, Virginia 22313-1450



Sir:

It is requested that a Certificate of Correction be issued correcting printing errors appearing in the above-identified United States patent. One copy of the text of the Certificate in the suggested form is enclosed.

As some of the errors listed are due to Applicant's mistake, please charge our credit card in the amount of \$100.00 to cover the Certificate fee.

Issuance of the Certificate of Correction would neither expand nor contract the scope of the claims, and re-examination is not required.

Respectfully submitted,  
HOPE BALDAUFF HARTMAN, LLC  
/Steven Koon Hon Wong/

Date: June 6, 2008

By: "Steven" Koon Hon Wong  
Reg. No. 48,459

Hope Baldauff Hartman, LLC  
1720 Peachtree Street, N.W.  
Suite 1010  
Atlanta, Georgia 30309  
(404) 815-1900

UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTION

PATENT NO. : 7,346,711 B1

PAGE 1 of 1

ISSUE DATE: March 18, 2008

APPLICATION NO.: 10/661,723

DATED : September 12, 2003

INVENTOR(S) : Sandip Datta Roy and Kevin Moore

**It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:**

Beginning in Column 2, line 60, and ending with Column 2, line 63 should read:

When The BIOS program executing on the processor reads a status register destination for the IDE drive and detects whether data read from the status register destination has a predefined value.

In the Claims

Beginning in Column 10, line 35, and ending with Column 10, line 38 should read:

14. upon the data read from the status register destination  
not having the first predefined value, return a second  
indication that an IDE drive is connected to the  
intelligent drive electronics channel;

MAILING ADDRESS OF SENDER:

Hope Baldauff Hartman, LLC  
Attn: "Steven" Koon Hon Wong  
1720 Peachtree Street, N.W., Suite 1010  
Atlanta, Georgia 30309

PATENT NO. 7,346,711 B1

Docket No. 60046.0062US01

No. of add'l copies

0

**53377**

PATENT TRADEMARK OFFICE